



FTBx-8870 Report

FAIL

Report Header: EXFO Inc.
Report Title:
Report Date: 9/29/2020 3:02:11 PM
Type: EtherSAM (Y.1564)

Job Information

Job ID:
Circuit ID: COL/WTN/ETH00006291.0
Contractor Name: Rainier Connect
Customer Name: grandcouleedam-k12
Operator Name: daniel dh
Comment:

Table of contents

SUMMARY	1
TEST RESULTS	5
TEST SETUP	7
FUNCTIONS	10
SYSTEM INFORMATION	13
LOGGER	17

SUMMARY

Results Summary

Test Status	
Service Configuration Test Status	Completed, Fail
Service Performance Test Status	Completed, Fail
Pass/Fail Verdict	FAIL
Start Time	9/29/2020 02:47:43 PM
Duration	00d:00:04:19
Test Recovery	0

EtherSAM

Services Summary			
	Service Name	Service Configuration Test	Service Performance Test
1	Service 1	FAIL	FAIL

Service Configuration Summary							
	Service Name	Direction	Frame Loss Rate	Max Jitter (ms)	Max Latency (ms)	Max Throughput (Mbit/s)	Service Verdict
1	Service 1	L->R	4.9E-03	1.30298		945.27	FAIL
		R->L	2.1E-05	0.08425	11.32703	949.99	PASS

Service Performance Summary							
	Service Name	Direction	Frame Loss Rate	Max Jitter (ms)	Max Latency (ms)	Avg Throughput (Mbit/s)	Service Verdict
1	Service 1	L->R	9.1E-03	3.19015		941.34	FAIL
		R->L	4.1E-05	0.07839	12.78687	949.96	PASS

VLAN Preservation	No Mismatch Detected
--------------------------	----------------------

RX Power Level		
	Min	Max
Power Range (dBm)	-15.0	0.5
RX Power Level (dBm)	-2.7	-2.7

RX Frequency		
	Max Negative Offset	Max Positive Offset
Frequency Offset (ppm)	-0.5	0.0

Alarms/Errors

Alarms/Errors List	
Active/Historical Alarms/Errors	Frame Loss

Interface	
Alarms	Seconds
LOS	0
Frequency	0

Ethernet	
Alarms	Seconds
Link Down	0
Local Fault Detected	0
Local Fault Received	0
Remote Fault	0

Errors	Seconds	Count	Rate
Block	0	0	0.00E00
FCS	0	0	0.00E00
Jabber	0	0	0.00E00
Oversize	Disabled		
Runt	0	0	0.00E00
Undersize	0	0	0.00E00
Total		0	

Clock Sync	
Alarm	Seconds
LOC	0

IP/UDP/TCP			
Errors	Seconds	Count	Rate
IP Checksum	0	0	0.00E00
UDP Checksum	0	0	0.00E00
TCP Checksum	0	0	0.00E00
Total		0	

Setup Summary

Application Type	EtherSAM (Y.1564)
------------------	-------------------

Interface	Port 1
Interface/Rate	10GE LAN
Connector	SFP+

Flow Control	None
--------------	------

EtherSAM

DTS Enabled	
Remote ID	MAX-860G81
Nat Router Detection	No NAT
Local WAN IP	N/A
Pass/Fail Verdict	Enabled

Sub-Tests			
Service Configuration Test		Service Performance Test	
Ramp Test	Enabled	Status	Enabled
Burst selection	Disabled	Duration	00d:00:10:28
Duration	00:00:20		

Ramp	
Step Time (s)	5
Step Values	
1	50 %
2	75 %
3	90 %
4	100 %

Services

Total Committed TX Rate (Mbit/s)	L->R	950.00
	R->L	950.000

Services Summary									
	Service Name	Profile	Frame Size (Bytes)	Direction	CIR (Mbit/s)	Max Jitter (ms)	Max Latency (ms)	Frame Loss Rate	CBS (Bytes)
1	Service 1	Data	Random	L->R	950.00	2.00000		1.0E-04	--
				R->L	950.000	2.00000	28.00000	1.0E-04	

TEST RESULTS

Ethernet Traffic

Frame Type	TX Count	RX Count
Multicast	0	10
Broadcast	2	2
Unicast	33422665	33424547
Non-Unicast	2	12
Total	33422667	33424559

Frame Size (Bytes)	RX Count	%
< 64	0	0.0
64	419	0.0
65 - 127	1380509	4.1
128 - 255	2947907	8.8
256 - 511	5898107	17.6
512 - 1023	11793031	35.2
1024 - 1518	11404586	34.1
> 1518	0	0.0
Total	33424559	

Detailed EtherSAM Results

Service Configuration Test

Service 1 : Service 1

Committed Steps						
Committed Step	Direction	Frame Loss Rate	Max Jitter (ms)	Max Latency (ms)	Verdict	Avg Throughput (Mbit/s)
1-50%CIR	L->R	0.0E-00	0.15760	9.91182	PASS	475.00
	R->L	0.0E-00	0.08425		PASS	474.990
2-75%CIR	L->R	0.0E-00	0.19997	10.11813	PASS	712.49
	R->L	2.1E-05	0.08019		PASS	712.480
3-90%CIR	L->R	3.1E-04	1.00427	11.32703	FAIL	854.73
	R->L	0.0E-00	0.06277		PASS	855.000
CIR	L->R	4.9E-03	1.30298	10.80161	FAIL	945.27
	R->L	0.0E-00	0.06199		PASS	949.990

Service Performance Test

Service 1 : Service 1

	Direction	Average	Minimum	Maximum	Estimate
Throughput (Mbit/s)	L->R	941.34	858.76	951.08	N/A
	R->L	949.96	947.75	950.08	N/A
Jitter (ms)	L->R	0.00074	< 0.00001	3.19015	0.00033
	R->L	0.00863	< 0.00001	0.07839	0.00869
Latency (ms)	Round-trip	9.28890	9.04068	12.78947	N/A
		Seconds	Count	Rate	
Frame Loss	L->R	136	280736	9.1E-03	
	R->L	26	1257	4.1E-05	
Out-of-Sequence	L->R	0	0	0.0E00	
	R->L	0	0	0.0E00	

TEST SETUP

Clock Synchronization

Clock Mode	Internal
------------	----------

Detailed Services Configuration

IP Version	IPv4	
Layer Mode	Mixed	
Global Pass/Fail Verdict	Enabled	
	L->R	R->L
Total Committed TX Rate (Mbit/s)	950.00	950.000

Service 1

Service Profile	
Service Name	Service 1
Profile	Data
Frame Size Type	Random

SLA Parameters		
	L->R	R->L
Information Rate		
CIR (Mbit/s)	950.00	950.00
Burst Size		
Performance Criteria		
Max Jitter (ms)	2.00000	2.00000
Max Latency (ms)	28.00000	28.00000
Frame Loss Rate	1.0E-04	

Test Parameters		
	L->R	R->L

Framing		
Frame Format	Ethernet II	
Network Layer	IPv4	
Transport Layer	UDP	
	L->R	R->L
VLAN	None	None

Addressing

		MAC	IP Address	UDP Port
L->R	Source	00:03:01:F8:22:D8	10.112.0.1 / 255.255.255.0	49184
	Destination	00:03:01:F8:29:81	10.112.0.100	7
R->L	Source	00:03:01:F8:29:81	10.112.0.100 / 255.255.255.0	7
	Destination	00:03:01:F8:22:D8	10.112.0.1	49184

	L->R	R->L
EtherType	0x0800	0x0800
Automatic IP (DHCP)	Disabled	No
TTL	128	128
TOS	0x00	0
Default Gateway	Disabled	Disabled

FUNCTIONS

Ping & Trace Route

Network	
Source MAC Address	00:03:01:F8:22:D8
Source IP Address	10.112.0.1 (Stream 1)
Destination IP Address	10.112.0.100

Ping	
Timeout (ms)	500
Delay (ms)	1000
Data Size (Bytes)	32
TTL	128
Type Of Service (TOS)	0x00

Ping Results		
No.	Status	Reply Details
4398	Successful	IP=10.112.0.100, Bytes=32, Time=9 ms, TTL=127
4399	Successful	IP=10.112.0.100, Bytes=32, Time=9 ms, TTL=127
4400	Successful	IP=10.112.0.100, Bytes=32, Time=9 ms, TTL=127
4401	Successful	IP=10.112.0.100, Bytes=32, Time=9 ms, TTL=127
4402	Successful	IP=10.112.0.100, Bytes=32, Time=9 ms, TTL=127
4403	Successful	IP=10.112.0.100, Bytes=32, Time=9 ms, TTL=127
4404	Successful	IP=10.112.0.100, Bytes=32, Time=9 ms, TTL=127
4405	Successful	IP=10.112.0.100, Bytes=32, Time=9 ms, TTL=127
4406	Successful	IP=10.112.0.100, Bytes=32, Time=9 ms, TTL=127
4407	Successful	IP=10.112.0.100, Bytes=32, Time=9 ms, TTL=127
4408	Successful	IP=10.112.0.100, Bytes=32, Time=9 ms, TTL=127
4409	Successful	IP=10.112.0.100, Bytes=32, Time=9 ms, TTL=127
4410	Successful	IP=10.112.0.100, Bytes=32, Time=9 ms, TTL=127

4411	Successful	IP=10.112.0.100, Bytes=32, Time=9 ms, TTL=127
4412	Successful	IP=10.112.0.100, Bytes=32, Time=9 ms, TTL=127
4413	Successful	IP=10.112.0.100, Bytes=32, Time=9 ms, TTL=127
4414	Successful	IP=10.112.0.100, Bytes=32, Time=9 ms, TTL=127
4415	Successful	IP=10.112.0.100, Bytes=32, Time=9 ms, TTL=127
4416	Successful	IP=10.112.0.100, Bytes=32, Time=9 ms, TTL=127
4417	Successful	IP=10.112.0.100, Bytes=32, Time=9 ms, TTL=127
4418	Successful	IP=10.112.0.100, Bytes=32, Time=9 ms, TTL=127
4419	Successful	IP=10.112.0.100, Bytes=32, Time=9 ms, TTL=127
4420	Successful	IP=10.112.0.100, Bytes=32, Time=9 ms, TTL=127
4421	Successful	IP=10.112.0.100, Bytes=32, Time=9 ms, TTL=127
4422	Successful	IP=10.112.0.100, Bytes=32, Time=9 ms, TTL=127
4423	Successful	IP=10.112.0.100, Bytes=32, Time=9 ms, TTL=127
4424	Successful	IP=10.112.0.100, Bytes=32, Time=9 ms, TTL=127
4425	Successful	IP=10.112.0.100, Bytes=32, Time=9 ms, TTL=127
4426	Successful	IP=10.112.0.100, Bytes=32, Time=9 ms, TTL=127
4427	Successful	IP=10.112.0.100, Bytes=32, Time=9 ms, TTL=127
4428	Successful	IP=10.112.0.100, Bytes=32, Time=9 ms, TTL=127
4429	Successful	IP=10.112.0.100, Bytes=32, Time=9 ms, TTL=127
4430	Successful	IP=10.112.0.100, Bytes=32, Time=9 ms, TTL=127
4431	Successful	IP=10.112.0.100, Bytes=32, Time=9 ms, TTL=127
4432	Successful	IP=10.112.0.100, Bytes=32, Time=9 ms, TTL=127
4433	Successful	IP=10.112.0.100, Bytes=32, Time=9 ms, TTL=127
4434	Successful	IP=10.112.0.100, Bytes=32, Time=9 ms, TTL=127
4435	Successful	IP=10.112.0.100, Bytes=32, Time=9 ms, TTL=127
4436	Successful	IP=10.112.0.100, Bytes=32, Time=9 ms, TTL=127
4437	Successful	IP=10.112.0.100, Bytes=32, Time=9 ms, TTL=127
4438	Successful	IP=10.112.0.100, Bytes=32, Time=9 ms, TTL=127
4439	Successful	IP=10.112.0.100, Bytes=32, Time=9 ms, TTL=127
4440	Successful	IP=10.112.0.100, Bytes=32, Time=9 ms, TTL=127
4441	Successful	IP=10.112.0.100, Bytes=32, Time=9 ms, TTL=127
4442	Successful	IP=10.112.0.100, Bytes=32, Time=9 ms, TTL=127
4443	Successful	IP=10.112.0.100, Bytes=32, Time=9 ms, TTL=127
4444	Successful	IP=10.112.0.100, Bytes=32, Time=9 ms, TTL=127
4445	Successful	IP=10.112.0.100, Bytes=32, Time=9 ms, TTL=127
4446	Successful	IP=10.112.0.100, Bytes=32, Time=9 ms, TTL=127
4447	Successful	IP=10.112.0.100, Bytes=32, Time=9 ms, TTL=127
4448	Successful	IP=10.112.0.100, Bytes=32, Time=9 ms, TTL=127
4449	Successful	IP=10.112.0.100, Bytes=32, Time=9 ms, TTL=127
4450	Successful	IP=10.112.0.100, Bytes=32, Time=9 ms, TTL=127
4451	Successful	IP=10.112.0.100, Bytes=32, Time=9 ms, TTL=127
4452	Successful	IP=10.112.0.100, Bytes=32, Time=9 ms, TTL=127
4453	Successful	IP=10.112.0.100, Bytes=32, Time=9 ms, TTL=127

4454	Successful	IP=10.112.0.100, Bytes=32, Time=9 ms, TTL=127
4455	Successful	IP=10.112.0.100, Bytes=32, Time=9 ms, TTL=127
4456	Successful	IP=10.112.0.100, Bytes=32, Time=9 ms, TTL=127
4457	Successful	IP=10.112.0.100, Bytes=32, Time=9 ms, TTL=127
4458	Successful	IP=10.112.0.100, Bytes=32, Time=9 ms, TTL=127
4459	Successful	IP=10.112.0.100, Bytes=32, Time=9 ms, TTL=127
4460	Successful	IP=10.112.0.100, Bytes=32, Time=9 ms, TTL=127
4461	Successful	IP=10.112.0.100, Bytes=32, Time=9 ms, TTL=127
4462	Successful	IP=10.112.0.100, Bytes=32, Time=9 ms, TTL=127
4463	Successful	IP=10.112.0.100, Bytes=32, Time=9 ms, TTL=127
4464	Successful	IP=10.112.0.100, Bytes=32, Time=9 ms, TTL=127
4465	Successful	IP=10.112.0.100, Bytes=32, Time=9 ms, TTL=127
4466	Successful	IP=10.112.0.100, Bytes=32, Time=9 ms, TTL=127
4467	Successful	IP=10.112.0.100, Bytes=32, Time=9 ms, TTL=127
4468	Successful	IP=10.112.0.100, Bytes=32, Time=9 ms, TTL=127
4469	Successful	IP=10.112.0.100, Bytes=32, Time=9 ms, TTL=127
4470	Successful	IP=10.112.0.100, Bytes=32, Time=9 ms, TTL=127
4471	Successful	IP=10.112.0.100, Bytes=32, Time=9 ms, TTL=127
4472	Successful	IP=10.112.0.100, Bytes=32, Time=9 ms, TTL=127
4473	Successful	IP=10.112.0.100, Bytes=32, Time=9 ms, TTL=127
4474	Successful	IP=10.112.0.100, Bytes=32, Time=9 ms, TTL=127
4475	Successful	IP=10.112.0.100, Bytes=32, Time=9 ms, TTL=127
4476	Successful	IP=10.112.0.100, Bytes=32, Time=9 ms, TTL=127
4477	Successful	IP=10.112.0.100, Bytes=32, Time=9 ms, TTL=127
4478	Successful	IP=10.112.0.100, Bytes=32, Time=9 ms, TTL=127
4479	Successful	IP=10.112.0.100, Bytes=32, Time=9 ms, TTL=127
4480	Successful	IP=10.112.0.100, Bytes=32, Time=9 ms, TTL=127
4481	Successful	IP=10.112.0.100, Bytes=32, Time=9 ms, TTL=127
4482	Successful	IP=10.112.0.100, Bytes=32, Time=9 ms, TTL=127
4483	Successful	IP=10.112.0.100, Bytes=32, Time=9 ms, TTL=127
4484	Successful	IP=10.112.0.100, Bytes=32, Time=9 ms, TTL=127
4485	Successful	IP=10.112.0.100, Bytes=32, Time=9 ms, TTL=127
4486	Successful	IP=10.112.0.100, Bytes=32, Time=9 ms, TTL=127
4487	Successful	IP=10.112.0.100, Bytes=32, Time=9 ms, TTL=127
4488	Successful	IP=10.112.0.100, Bytes=32, Time=9 ms, TTL=127
4489	Successful	IP=10.112.0.100, Bytes=32, Time=9 ms, TTL=127
4490	Successful	IP=10.112.0.100, Bytes=32, Time=9 ms, TTL=127
4491	Successful	IP=10.112.0.100, Bytes=32, Time=9 ms, TTL=127
4492	Successful	IP=10.112.0.100, Bytes=32, Time=9 ms, TTL=127
4493	Successful	IP=10.112.0.100, Bytes=32, Time=9 ms, TTL=127
4494	Successful	IP=10.112.0.100, Bytes=32, Time=9 ms, TTL=127
4495	Successful	IP=10.112.0.100, Bytes=32, Time=9 ms, TTL=127
4496	Successful	IP=10.112.0.100, Bytes=32, Time=9 ms, TTL=127

4497	Successful	IP=10.112.0.100, Bytes=32, Time=9 ms, TTL=127
------	------------	---

Ping Statistics	
Packets Transmitted	4497
Packets Received	3301
Percentage Lost (%)	26.6
Minimum Round Trip Time (ms)	9
Maximum Round Trip Time (ms)	31
Average Round Trip Time (ms)	9

SYSTEM INFORMATION

Product Name	Power Blazer Series
Version	Power Blazer Series 1.60 SP1
Module ID	FTBx-8870
Slot ID	1
Software Product Version	1.60.1.101
	Power Blazer Series 1.60 SP1
Assembly Hardware Revision	B
Serial Number	1343184
Calibration Date	4/20/2020 8:28:00 PM

Pluggable Module

Module ID	SFP+
Vendor Name	WFS
Part Number	WFSP-1396-10-J
Serial Number	3172922861
Hardware Revision	1.0
Connector Type	LC
Speed	10G
Type/Compliance Code	LR, 10.0 km (SMF)
Wavelength	1310 nm
Mode	Single-Mode Fiber
Power Class	Power Class 1 Module (<= 1W max)
Temperature (Max)	32.4 °C

Software Options

DS1-FDL	DS1/1.5M Facility Data Link	Disabled
CPRI-10.1G	CPRI 10.1376 Gbit/s	Disabled
SDH	Synchronous Digital Hierarchy	Enabled
SONET	Synchronous Optical Network	Enabled
622M	622 Mbit/s	Disabled
eCPRI-10G	eCPRI over 10G Ethernet	Disabled
DSn	Digital Signal (DS1, DS3)	Disabled
PDH	Plesiochronous Digital Hierarchy (E1, E3, E4)	Disabled
155M	155 Mbit/s	Disabled
2488M	2.488 Gbit/s	Disabled
10G_LAN	Ethernet 10G LAN optical interface	Enabled
10G_WAN	Ethernet 10G WAN optical interface	Enabled
L2-Transparency	L2CP Handling Test in EtherSAM	Disabled
TCM	Tandem Connection Monitoring HO/LO	Disabled

TunableOptics	Tunable Wavelength Support for SFP+	Disabled
9953M	9.953 Gbit/s	Disabled
OTU1	Optical Transport Unit-1 (2.7 Gbit/s)	Disabled
OTU2	Optical Transport Unit-2 (10.7 Gbit/s)	Disabled
100Optical	Ethernet 100Base-FX (Optical) Interface	Disabled
GigE_Optical	Ethernet 1000Base-X (Optical) Interface	Enabled
GigE_Electrical	Ethernet 1000Base-T (Electrical) Interface	Enabled
FC-1X	Fibre Channel 1X	Disabled
FC-2X	Fibre Channel 2X	Disabled
TCP-THPUT	Tcp Throughput Test Application	Disabled
100electrical	Ethernet 100Base-TX (Electrical) Interface	Enabled
10electrical	Ethernet 10Base-T (Electrical) Interface	Enabled
ODUMUX	ODU Multiplexing Payload Type 20 and 21	Disabled
FC-10X	Fibre Channel 10X	Disabled
OTU2-1e-2e	Optical Transport Unit-2 Overclocked (11.049/11.096 Gbit/s)	Disabled
FC-4X	Fibre Channel 4X	Disabled
ADV-FILTERS	Advanced Filtering	Disabled
MPLS	MPLS Encapsulation (10GE and less)	Disabled
IPV6	Internet Protocol Version 6 (IPv6) (10GE and less)	Disabled
OTN-INTR-THRU	OTN Intrusive Through Mode	Disabled
EoOTN	Ethernet over Optical Transport Network	Disabled
ETH-THRU	Through Mode Test Application	Disabled
OTU2-1f-2f	Optical Transport Unit-2 Overclocked (11.270/11.317 Gbit/s)	Disabled
Cable_Test	Cable Test	Disabled
ODU0	OTN ODU0	Disabled
ETH-CAPTURE	Ethernet Frame Capture for Advanced Troubleshooting	Disabled
ODUflex	OTN ODUflex	Disabled
TRAFFIC-SCAN	Traffic Scan	Disabled
52M	52 Mbit/s	Enabled
NI-CSU	NI/CSU Emulation	Disabled
FC-8X	Fibre Channel 8X	Disabled
CPRI	CPRI 2.4576 Gbit/s and 3.072 Gbit/s	Disabled
OBSAI	OBSAI 3.072 Gbit/s	Disabled
1588PTP	1588 Precision Time Protocol	Disabled
SyncE	Synchronous Ethernet	Disabled
ETH-OAM	Carrier Ethernet OAM Test Application	Disabled
CPRI-1.2G	CPRI 1.2288 Gbit/s	Disabled
CPRI-4.9G	CPRI 4.9152 Gbit/s	Disabled
CPRI-6.1G	CPRI 6.144 Gbit/s	Disabled
CPRI-9.8G	CPRI 9.8304 Gbit/s	Disabled
DUAL-PORT	Dual Port Test	Disabled
RFC6349	RFC 6349 Test Application (10GE and less)	Disabled
iSAM	Intelligent Service Activation Methodology	Disabled
PoE	Power Over Ethernet	Disabled
LINK-OAM	Link OAM	Disabled
DP-CPRI	Dual Port CPRI	Disabled

TST-OAM	Test Over Service OAM	Disabled
G82751	ITU-T G.8275.1 Profile	Disabled
iOptics	Intelligent Pluggable Optic Test Application	Disabled
EoE	Ethernet over Ethernet Encapsulation (10GE and less)	Disabled
PBBTE	Provider Backbone Bridge Encapsulation (10GE and less)	Disabled
RFC6349-EXFOWorx	Enables EXFO Worx Interop Operation Mode	Disabled
GCC-BERT	OTN Overhead BERT and Synchronization Validation	Disabled
OBSAI-1.5G	OBSAI 1.536 Gbit/s	Disabled
OBSAI-6.1G	OBSAI 6.144 Gbit/s	Disabled
DTS-NAT	NAT Traversal for DTS applications	Disabled

LOGGER

ID	Start Time	Event	Duration	Details
1	09/29 02:47:43 PM	Test Started		2020-09-29
2	09/29 02:47:50 PM	Service Configuration te		2020-09-29
3	09/29 02:48:18 PM	Service 1 Fail		1 Service 1
4	09/29 02:48:26 PM	Service Performance tes		2020-09-29
5	09/29 02:48:38 PM	Frame Loss	00:00:01	4/4 S(1)
6	09/29 02:48:40 PM	Frame Loss	00:00:01	28/32 S(1)
7	09/29 02:48:54 PM	Frame Loss	00:00:01	13/45 S(1)
8	09/29 02:48:56 PM	Frame Loss	00:00:01	5/50 S(1)
9	09/29 02:49:01 PM	Frame Loss	00:00:01	15/65 S(1)
10	09/29 02:49:13 PM	Frame Loss	00:00:01	17/82 S(1)
11	09/29 02:49:18 PM	Frame Loss	00:00:02	169/251 S(1)
12	09/29 02:49:22 PM	Frame Loss	00:00:01	23/274 S(1)
13	09/29 02:49:42 PM	Frame Loss	00:00:01	69/343 S(1)
14	09/29 02:49:47 PM	Frame Loss	00:00:01	57/400 S(1)
15	09/29 02:50:03 PM	Frame Loss	00:00:01	18/418 S(1)
16	09/29 02:50:11 PM	Frame Loss	00:00:01	4/422 S(1)
17	09/29 02:50:24 PM	Frame Loss	00:00:01	29/451 S(1)
18	09/29 02:50:29 PM	Frame Loss	00:00:01	30/481 S(1)
19	09/29 02:50:44 PM	Frame Loss	00:00:02	82/563 S(1)
20	09/29 02:51:05 PM	Frame Loss	00:00:01	21/584 S(1)
21	09/29 02:51:25 PM	Frame Loss	00:00:02	19/603 S(1)
22	09/29 02:51:46 PM	Frame Loss	00:00:01	4/607 S(1)
23	09/29 02:51:52 PM	Frame Loss	00:00:01	24/631 S(1)
24	09/29 02:51:55 PM	Frame Loss	00:00:08	626/1257 S(1)
25	09/29 02:52:02 PM	Service 1 Fail		1 Service 1
26	09/29 02:52:02 PM	Test Stopped		 FAIL